




Hydra-Extractors HE-9

P/N	Description
13650	Top Bearing, HE-9
41688	Drive Motor, 5 HP, HE-9
14060	Drive Belt, 2 Required, B46
14070	Drive Belt, 2 Required, B51
81045	Bottom Plate 
81050	Bottom Pin Assembly w/ Hardware 

<p>81400</p>	<p>Bottom Bushing</p> 
<p>82790</p>	<p>Bottom Gasket</p>
<p>86570</p>	<p>Screen Assembly</p> 
<p>86720</p>	<p>Screw Assembly</p> 
<p>16010-1</p>	<p>Brush Only, 5 Revolutions Needed (Order 5)</p>
<p>51700-1</p>	<p>Gear Reducer</p>

9 Inch Screw	Rebuild (Full Pitch) + HE-9
9 Inch Screw	Rebuild (Half Pitch)

**Please call/fax/email price quotes and orders to:
717-397-5100 x 133 for Scott Witmer in Parts
717-291-0878 for Parts Fax
Or email to: parts@somatcompany.com**