




SP-50

P/N	Description
24950	HyPoint Rotating Cutting Ears (2 Req'd Sold Each)
	
32450	Flinger, Drive Motor
	
41679	Motor, 5HP Drive (ODP) "Open, Drip Proof" Baldor
41680	Motor, 5HP Drive (TEFC) "Totally Enclosed, Fan Cooled" Reuland
54311	Mechanical Seal, 1-1/8" Drive shaft
80985	Chipper Blade With Hardware
	
80988	HyPoint Stationary Cutter (3 Req'd, Sold Each)
	
80993	Rotating Blade With Hardware
	

80998	Top Block	
84150	Puller, Impeller (Tool)	
85485	Impeller Assembly (Replaces #84095)	
85555	HyPoint Impeller (SP-50), Assy (rotating blades not shown)	
85550	HyPoint Impeller (SP-50)	

87061	Hypoint Security Ring (SP-50), Assy	
89711	Installer, Mechanical Seal (Tool)	
80999-2	Stationary Cutter	
86280-2	Top Ring (No Pockets)	
86280-4	Top Ring (With Pockets)	
86281-2	Bottom Ring	
87610-2	Security Ring Assembly	
87630-2	Segment, Security Ring 7/16" Holes	
87630-3	Segment Security Ring 5/8" Holes	

Please call/fax/email price quotes and orders to:

717-397-5100 x 133 for Scott Witmer in Parts

717-291-0878 for Parts Fax

Or email to: parts@somatcompany.com